

General advice on how to handle the TCTControl box

The TCTControl boxes are available in 4 or 6 axes option. Both versions come with stepper motor outputs and: 1x USB client, 1x USB host, 1x 10/100 ethernet, 1x E-stop input, 6x Signal input (i.e. for limit switches), 1x spindle control output, 2x relais output, 1x UniPrint3D port and 1x Power supply connector (AC adapter included in delivery).

Note the following:


- 1) Never use the TCTControl box without the 24 V power supply. (24 V, 5A power adapter include)
- 2) Never plug or unplug the step motors during operation. The "MACHINE" [3] must be switched off first. This also applies to all other inputs and outputs on the rear panel.
- 3) Use the box in a dry environment. The ambient temperature should be between -10 and +35 degrees celsius (14 and 95 degrees Fahrenheit).
- 4) Only use the step motors supplied by us.
- 5) Turn on "MACHINE" only after the control software machinekit® (Cetus/machineface®) has been started. To simulate projects on the screen turn off "MACHINE".



- 1 ... boot/shut down button (software part)
- 2 ... connection to the PC (USB)
- 3 ... ON/OFF (stepper motor driver part)
The stepper motor drivers part is independent from the software part and must be switched on/off separately.
- 4 ... network connection
- 5 ... USB port to connect Wlan adapter, flash drives,
- 6 ... status LEDs:



- Blue LED shine**
TCTControl software part is running
- Blue and red LED shine**
CNC application is running
software status -> machine power on (ON/OFF button without function)



- 7 power connector (24 V / 5 A adapter)
- 8 machine axes (stepper motor)
- 9 input eg. reference switches
- 10 ... E-stop (art.no. 164 425 CNC)
- 11 ... connection to UniPrint3D
- 12 ... relais outputs 1 + 2 (signal 24 V)
- 13 ... spindle control output (0 - 10 V)



Connect the 24 V power supply to the TCTControl.

Use the supplied USB cable to connect TCTControl to a free USB port.

Wait until it shows under Windows.

(PC with Windows 7 or higher)



For Win8 and Win10 user:

a) disable the driver signature verification before you continue.


You can find many tutorials on the internet.

or


b) follow the video <https://youtu.be/y-rFVQplUWs>

(In this case, continue with „**Start CNC application 4.2.2**“.)


open folder „Windows“
on TCTControl



go to „Drivers“




start „BONE_DRV“ for 32bit OS
start „BONE_D64“ for 64bit OS




OPTIONAL


Under „Systeminformation“ you can find the information.



click YES




click CONTINUE




YES install this driver!

(This needs to be continued several times.)


Also confirm all firewall and virus scanner messages concerning TCTControl.



click INSTALL




click COMPLETE



Variant A:

Run the machinekit-client directly from TCTControl.


Go to
TCTControl\Windows\
start “Start_machinekit-client.bat”



Variant B:

Run the machinekit-client from your Windows system.


Go to
TCTControl\Windows\Utils\
copy the folder “MachinekitClient”
to you system (eg.: to the Desktop),
Open the folder and start
“machinekit-client.exe”




Machinekit-client starts




If you used variant B, then you must enter the IP of the TCTControl, at the first start. Click at “+”




The standard IP of the TCTControl is: **192.168.7.2**




Few seconds later, the machinekit-client shows the connected TCTControl.




To change the language, click on the flag and select your preferred language.



Go to the machine menu.
Click on
“Machinekit Launcher”




All available machine configurations are now being displayed.



Use the STAR to rank machines up.




To start a machine configuration click on it.



The starting process takes some seconds.






1 menu bar

- A1) File -> Open File --- To open file from PC or network and upload it to the TCTControl
- A2) File -> Open File from Machine ---- To open file that already stored on TCTControl
- A3) File -> Edit File with System Editor --- To edit the currently loaded G-Code file.
- A4) File -> Reopen file --- After editing an open file, reopen it to update.
- A5) File -> Edit Tool Table --- Add and remove tools.
- A6) File-> Disconnect from Session --- Go back to the Launcher; without shutting down the running machine configuration.
- A7) File-> Shutdown Session --- Shut down the machine configuration and go back to launcher.
- A8) File-> Exit User Interface --- Closes the machinekit-client application, the machine configuration remains running.
- B) Machine --- For more details take a look at point 2 „icon bar“
- C) View --- Setup the user interface

2 icon bar

- | | | | | | |
|--|---------------------------|---|-----------------------|---|-----------------------|
|  | E-Stop ON/OFF |  | machine ON/OFF |  | open file from PC |
|  | open file from TCTControl |  | reload open file |  | start working process |
|  | process only next line |  | working process pause |  | stop working process |
|  | zoom function for preview |  | change preview view |  | reset live plot |

3 control area

Can only be used if E-Stop is OFF and machine is ON.

A) Manual

May slightly vary depending on the machine configuration.




- 1 axis selection
- 2 direction of movement
- 3 distance of movement (0.001 up to continuous)
- 4 referencing the axis (e.g. set zero point,)
- 5 speed of the movement (feed rate)
- 6 relais (cooling, dust extraction, ...)
- 7 headspindel (ON/OFF, rpm, direction of rotation
available functions depend on the motor used.

B) MDI (manual data input)

Can only be used if all axes are referenced.

- 1 enter one command line (e.g. G0 X10 y10)
- 2 to execute inputted command, click here
- 3 history of entered command lines

If you click on a line in the history, the line will be entered again (1).



4 information area


DRO (digital readout)

X, Y, (depends on the machine used)

show the actual positions of the axes. If the background is red, the axis is not referenced (homed). If the background is green, the axis is homed.


Vel actual speed of the machine movement.

DTG distance to go




Preview

shows additionally all tool paths of the open G-Code files




marks referenced (homed) axis.




5 Configuration area

- 1 Feed Override (override programmed feed rate [F] of loaded G-Code file)
- 2 Spindle Override (override programmed spindle speed [S])
- 3 Maximum Velocity (override the maximal speed of the machine)



6 loaded G-Code file and 7 info line



- 1 Currently loaded G-Code file
- 2 Machine status ON/OFF
- 3 Currently loaded tool
- 4 Position mode
- 5 File name of the currently loaded G-Code file.


Machine: UNI-FRAES-V3

File: Sample_M1.ngc


Raw material: Special colored Acrylic, 50x50x3 mm[art.no.: 166PLEXS]

Tool: 1.6 mm end mill

-) Mark the center of the square (raw material)
-) Use the clamping jaws to fix the raw material. Protect the machine table by placing a second plate (plywood or acrylic, thickness min. 3 mm) beneath the raw material.



-) Start UNI-FRAES-V3 (machinekit-client)
 - 1) Deactivate the E-Stop
 - 2) Machine power ON
 - 3) Open G-Code file stored on machine



[illegible]

- [illegible]

The screenshot displays the SolidWorks CAD environment. The top-left corner shows the 'Features' tab, which is highlighted by a red arrow. The main 3D view shows a mechanical part with various dimensions and features. A green arrow points to a specific feature in the model. The bottom-left corner shows a list of features, with the first feature highlighted by a red circle containing the number 1.


1. Material: steel, 304 (2x mm)
 2. (Base) > 1.0 mm end (m3)
 3. (Base) > 1.0 mm end (m3)
 4. 1.0 mm end (m3)
 5. 1.0 mm end (m3)
 6. 1.0 mm end (m3)
 7. 1.0 mm end (m3)
 8. 1.0 mm end (m3)
 9. 1.0 mm end (m3)
 10. 1.0 mm end (m3)
 11. 1.0 mm end (m3)
 12. 1.0 mm end (m3)
 13. 1.0 mm end (m3)
 14. 1.0 mm end (m3)
 15. 1.0 mm end (m3)
 16. 1.0 mm end (m3)
 17. 1.0 mm end (m3)
 18. 1.0 mm end (m3)
 19. 1.0 mm end (m3)
 20. 1.0 mm end (m3)

•) Simulate the G-Code

- 1 ... Turn MACHINE OFF!
- 2 ... Select the X axis
- 3 ... click HOME

Repeat the process with Y and Z axis.


Now all 3 axes are homed.



- 1) click on „PLAY“

The simulation is running.

- 2) click on „STOP“ to stop the simulation



Cetus - start a sample file

[milling • cutting • turning]

4.2.2.2

•) Run the G-Code at the milling machine

1 ... move the milling head (X/Y axis) to the zero position at the raw material.

2 ... put a thin paper between raw material and milling head. Go down with the Z axis and stop if the paper get stuck.


3 ... now the milling head stay at the zero position.

For that work you can move the axes manual (using the hand wheels - MACHINE at the TCTControl must be OFF!

or

Use the Cetus software interface to move the axes - MACHINE at the TCTControl must be ON!

4 ... turn MACHINE ON at the TCTControl



5 ... select the X axis


6 ... click HOME

Repeat the process with Y and Z axis.


Now all 3 axes are homed.



If a axis is already homed, no problem, home it again.



- 7 ... switch to MDI
- 8 ... enter: G0 z2
- 9 ... click GO



- 10 ... turn the milling motor ON




- 1) click on „PLAY“

The milling process starts.

- 2) to stop the machine (milling process) click on one of the three icons

- a) E-stop
- b) Machine power
- c) Stop



When the milling operation is finished turn the milling motor OFF!



Exercise 1


Machine: UNI-FRAES-V3

File: ../examples/exerc1-simple-square.ngc


Raw material: Special colored Acrylic, 50x50x3 mm[art.no.: 166PLEXS]

Tool: 1.6 mm end mill

-) Mark the center of the square (raw material)
-) Use the clamping jaws to fix the raw material. Protect the machine table by placing a second plate (plywood or acrylic, thickness min. 3 mm) beneath the raw material.



It is similar to the Sample_M1.ngc file



Exercise 2

Machine: UNI-FRAES-V3


File: .../examples/exerc2-3circlrs-g41_g42.ngc

Raw material: Special colored Acrylic, 50x50x3 mm[art.no.: 166PLEXS]

Tool: 1.6 mm end mill

-) Mark the center of the square (raw material)
-) Use the clamping jaws to fix the raw material. Protect the machine table by placing a second plate (plywood or acrylic, thickness min. 3 mm) beneath the raw material.

Programmed diameter of the circles is 6 mm.



1st circle (on right position):

It is without tool diameter compensation. The diameter of the cut out part is $6 - 1.6 = 4.4$ mm

The diameter of the cuted hole at the raw material is $6 + 1.6 = 7.6$ mm

2nd circle (in the middle):


With tool diameter compensation. The diameter of the cut out part is $6 - 1.6 - 1.6 = 2.8$ mm

The diameter of the cut hole in the material is 6 mm

3rd circle (on the left position):

It is with tool diameter compensation. **The diameter of the cut out part is 6 mm.**

The diameter of the cut hole in the material is $6 + 1.6 + 1.6 = 9.2$ mm



Experiment

Now replace the milling head at your milling machine - use for example a 1.2 mm end mill.

For tool number take a look at your tool table (t50 = 1.2 mm end mill)

Now „File =>Edit file with System Editor“, change the tool number from T55 to T50

Save as => exerc2-3circlrs-g41_g42-A.ngc ==> on the Desktop ==> open the new files in CETUS

Use a new raw material and cut the circles again (don't forget to update the zero point).

The diameters of the cuted hole (circle 2) and the cut out part (circle 3) will be also 6 mm.

It was only one small change at the G-Code file necessary!

Exercise 3


Machine: UNI-FRAES-4

File: ../examples/exerc3-BuildingBrick_Uni-fraes4-1.ngc

Raw material: Special milling foam, 50x25x25 mm[art.no.: 166FOAM S]


Tool: 1.6 mm end mill

-) Mark the zero point (raw material)
-) Use the 4 jaw chuck to fix the raw material.



After successfully milling this project the first time, try the following:

- Go to „MDI“
- Enter
`G0 a180 => „GO“`
- Go to „MANUAL“
- Home A axis again!
- Now you can start the milling file again.



Exercise 4

Machine: UNI-FRAES-V3

File: ../examples/exerc4-100-call-a-subroutine-sample.ngc

Raw material: plywood or acrylic, dimensions depending on the selected parameters

Tool: 1.6 mm end mill

Preparation

• Start the files.bat file at TCTControl/Windows/TOOLS/

• When asked for a password use: machinekit

The left part of the „WinSCP“ window is the file system of your PC. The right part is the file system of the TCTControl.

• Go to nc_files/examples

• Copy following files to the folder nc_files:

100.ngc



exerc4-100-call-a-subroutine-sample.ngc

• Open the exerc4-100-call-a-subroutine-sample.ngc file in CETUS

See comments in file exerc4-100-call-a-subroutine-sample.ngc !!!

To learn what the parameters like [-8] [8] [3] [3.5] [4] [2] mean, please read the comments in 100.ngc.

Experiment with different parameters.



Exercise 5


Machine: UNI-FRAES-V3

File: ../examples/exerc5-var-cicles.ngc


Raw material: Special colored Acrylic, 50x50x3 mm[art.no.: 166PLEXS]

Tool: 1.6 mm end mill

-) Mark the center of the square (raw material)
-) Use the clamping jaws to fix the raw material. Protect the machine table by placing a second plate (plywood or acrylic, thickness min. 3 mm) beneath the raw material.



Showing circle segments with G2.



Required hardware

Unimat CNC 3-axis vertical milling machine, CNC-rotating axis [164300 CNC], clamping device (e.g.: collet, 3-jaw chuck,), TCTControl [TCTCONT4 or TCTCONT6]

Requirements for the workpiece

The area to be engraved must have a consistent diameter.

1) Calculating the "SCALE" for the machine configuration (.ini file)

-) CNC-rotation axis [164300CNC]: 1 (micro) Step $\triangleq$ 17,7°
-) cylinder diameter $\varnothing$ D [mm]
circumference U [mm] ($U \triangleq 360^\circ$)
 π 3,14159

$$U = D \times \pi$$

$$1 \text{ mm} \triangleq 360 / U = S$$

$$\text{SCALE}_{[\text{step/mm}]} = 17,7^\circ \times S$$

1.1) Example of a cylinder with $\varnothing$ 14 mm

$$U = 14 \times 3,14159 = 43,98226$$

$$S = 360 / 43,98226 = 8,18512$$

$$\text{SCALE} = 17,7 \times 8,18512 = \underline{144,87662}$$

2) Customize the machine configuration file (e.g.: Uni-fraes-v3v2.ini)

-) Start files.bat
[TCTCONTROL\Windows\TOOLS\files.bat]
In the right area is the Linux file system of the TCTControl
-) The machine configurations files folder is
/home/machinekit/machinekit-configs/

-) Mark the configuration to be edited -> right mouse click -> Edit
-) Scroll to „#Second axis“

```
# Second axis
[AXIS_1]

TYPE = LINEAR
HOME = 0.000
MAX_VELOCITY = 5.0
MAX_ACCELERATION = 20.0
STEPGEN_MAX_VEL = 6.0
STEPGEN_MAX_ACC = 22.0
STEPGEN_MIN_VEL = 0.001
BACKLASH = 0.000
SCALE = -3200
MIN_LIMIT = -50.0
MAX_LIMIT = 50.0
FERROR = 0.500
```

-) Comment out the line „SCALE -3200“ with #

```
STEPGEN_MIN_VEL = 0.001
BACKLASH = 0.000
# SCALE = -3200
MIN_LIMIT = -50.0
MAX_LIMIT = 50.0
FERROR = 0.500
```

-) Add the following lines and save the file

```
STEPGEN_MIN_VEL = 0.001
BACKLASH = 0.000
# ORIGINAL - cross slide Y-axis
# SCALE = -3200
# diameter 14 mm
SCALE = 144.87662
MIN_LIMIT = -50.0
MAX_LIMIT = 50.0
```

-) Open Machinekit client and start machine configuration

3) Connect the Unimat CNC-rotating axis [164300CNC] to the Y-axis of the TCTControl

4) It is now possible to engrave a design (G code / X, Y, Z values) on the cylinder surface.

<https://inkscape.org>

Sample 1 - engraving into acrylic


raw material: acrylic plate ~ 50 x 50 x 3 mm

tool: end mill $\varnothing 1.0$ mm

optional: end mill $\varnothing 1.6$ mm




1) open "Inkscape®" then click on "File" --> "Document Properties..."




2) select at "Custom size" --> "Units" --> "mm".

enter for both "Width" and "Height" 50 after that close the window.




3) click on the magnifier icon "Zoom to fit page in window".




<https://inkscape.org>


4) click on the square icon "Create rectangles and squares".



5) at "Change" select "mm" then enter for "W" (width) 45 and for "H" (height) 30.




6) click on the arrow "Select and transform objects".




<https://inkscape.org>

7) select the rectangle (click on it).




8) Now that the rectangle is marked click on "Object" --> "Fill and Stroke".



9) in the window "Fill and Stroke" select "Fill" and click on "X" (No paint).

Attention:
The rectangle must be selected (marked).




<https://inkscape.org>

10) switch to "Stroke paint" and click on "Flat color" (1), then click "Blue" (2).

Attention:


The rectangle must be selected (marked).



11) write "255" and press "Enter". The contour color of the rectangle is now blue.

Attention:


The rectangle must be selected (marked).



12) click on "Path" --> "Object to Path" (vector). Now the rectangle is a vector graphic.

Attention:


The rectangle must be selected (marked).




<https://inkscape.org>

Create a new layer for the labeling:

13) click on "Layer" --> "Add Layer".




14) enter following name for the layer "font", then click on "Add".



15) click on "A" icon "Create and edit text objects".

Attention:

Layer "font" must be activated.




<https://inkscape.org>

16) click into the blue rectangle, then select a (Single Line Fonts) - for example "DINEng1Line". Write your text - for example:


The Cool Tool
CoolCNC

After that click on the arrow icon "Select and transform objects".




17) click on "Stroke paint" --> "Flat color".

Attention:
The text field must be activated (marked).




18) click on "red"



<https://inkscape.org>


19) enter "255" then click on "blue" and change value to "0" and press "Enter".

Attention:
The text field must be activated (marked).




20) click on "A" icon "Create and edit text objects", then click into the text field (The Cool Tool ...).

After that click on "Center".



21) click on the arrow icon "Select and transform objects".




<https://inkscape.org>

22) select the text field and place it in the middle of the blue rectangle.

Attention:


Please take care that the blue rectangle is at the center of the raw material. If it is not at the center, select the blue rectangle and the text field and place it again.



23) click on "Path" --> "Object to Path" (vector). Now the font is converted to a vector graphic.

Attention:


The text field must be activated (marked).



24) Why two layers?

For each cutting depth you need a separate layer. Here we have two different depths:

- 1) red text: 1.0 mm (engraving)
- 2) blue rectangle: 4.5 mm (raw material 4.0 mm - acrylic)



<https://inkscape.org>


Gcode Tools®

25) Orientation points
(zero point for the blue rectangle)

click on "Extensions" --> "Gcode tools" --> "Orientation points ..."

Attention:


- a) layer "Layer 1" must be activated.
- b) blue rectangle must be selected.




26) select "2-points mode" and
"mm". enter at "z depth" "-3.5".

Attention:

"z surface" remains "0.0".




27) click on "Apply" and then
"Close"



<https://inkscape.org>

28) select the layer "font"




29) Orientation points
(zero point for the red text)

click on "Extensions" --> "Gcode-
detools" --> "Orientation points ..."

Attention:


- a) layer "font" must be activated.
- b) red text must be selected.



30) select "2-points mode" and
"mm". enter at "z depth" "-1.0".

Attention:


"z surface" remains "0.0".




<https://inkscape.org>

31) The position of the zero point for layer "Layer 1" and layer "font" is the same (congruent).


Attention:
Do not move this point!



32) Tools library
activate "Layer 1" and select the blue rectangle (marked), then click on "Extensions" --> "Gcodetools" --> "Tools library"




33) select "cylinder"




<https://inkscape.org>


4) click on "Apply" then close the window - click on "Close"



2) click on the magnifier icon
"Zoom to fit drawing in window"




36) now you can see the "Tool window" for "Layer 1".




<https://inkscape.org>

37) place the "Tool window" near the blue rectangle, then click on the magnifier icon (Zoom to fit drawing in window).




38) click on the "A" icon (Create and edit text objects)




39) edit the following parameters in the "tool window":

diameter = 1
feed = 100
penetration feed = 25
depth step = 1.2




<https://inkscape.org>


40) activate layer "font" and select the red text (marked), then click on "Extensions" --> "Gcodetools" --> "Tools library"



41) select "cylinder" and click on "Apply" then close the window - click on "Close".




42) the new "Tool window" (window for layer "font") is magenta.




<https://inkscape.org>

43) click on the "A" icon (Create and edit text objects) and edit following parameters:

diameter = 1
feed = 100
penetration feed = 25
depth step = 0.5




44) check the order of the layers. click on "Layer" --> "Layers ...".




45) correct order: 1) font
2) Layer 1

If the order isn't correct, you can change the order. Select one of the two layers and then move it (with the arrows) up or down.




<https://inkscape.org>

46) click on the arrow icon "Select and transform objects", then select the engraving (red text) and the work piece (blue rectangle).




47) click on "Extensions" --> "Gcode Tools" --> "Path to Gcode ...".



48) click on "Preferences" and enter following parameters:

File: **sample-1.ngc**
Add numeric..... **"activate"** ☒
Directory: **/home/coolcnc/linuxcnc/nc_files**
("coolcnc" = username)
Z safe height **2.00**
Units **mm**
Post-processor **None**

click on "Path to Gcode"!




<https://inkscape.org>

49) check the parameters:


Biarc inter..... **0.100**
 Maximum splitting **4**
 Cutting order
subpath by subpath
 Depth funktion: **d**

click on "Apply" and then close the window- click on "Close"!



50) finished!

Now you can save the Inkscape file (click on "File" --> "Save"), after that you can close Inkscape®.




51) Open the generated G-Code file in CETUS (UNI-FRAES-V3).

<https://www.autodesk.com/products/fusion-360/students-teachers-educators>


Fusion 360 is a professional 3D CAD/CAM software for which AUTODESK offers free licenses for education.

Advanced designs, 2.5D drawings or 3D models can be constructed, the CAM functionality allows for generating G-code files.


Suitable post-processors and tool-tables make it compatible to the Machinekit CNC software.



Fusion 360 - CAD
(design process)



Fusion 360 - CAM
(set machining parameters)



Cetus - machinekit
(loaded G-Code)

Autodesk® Inventor® can also be used.

Cetus - UNI-FRAES-4 - tctcontrol.local. - 192.168.7.2

File Machine View Help

Manual [F3] MDI [F5]

Axis X Y Z A

- + Continuous

Home Touch Off

Jog Velocity 88.1 %

Coolant

Flood

Spindle

Stop CW

1 2 3 4 5 6 7 8

9 10 11 12

13 14 15 16

17 18 19 20

21 22 23 24

25 26 27 28

29 30 31 32

33 34 35 36

37 38 39 40

41 42 43 44

45 46 47 48

49 50 51 52

53 54 55 56

57 58 59 60

61 62 63 64

65 66 67 68

69 70 71 72

73 74 75 76

77 78 79 80

81 82 83 84

85 86 87 88

89 90 91 92

93 94 95 96

97 98 99 100

101 102 103 104

105 106 107 108

109 110 111 112

113 114 115 116

117 118 119 120

121 122 123 124

125 126 127 128

129 130 131 132

133 134 135 136

137 138 139 140

141 142 143 144

145 146 147 148

149 150 151 152

153 154 155 156

157 158 159 160

161 162 163 164

165 166 167 168

169 170 171 172

173 174 175 176

177 178 179 180

181 182 183 184

185 186 187 188

189 190 191 192

193 194 195 196

197 198 199 200

201 202 203 204

205 206 207 208

209 210 211 212

213 214 215 216

217 218 219 220

221 222 223 224

225 226 227 228

229 230 231 232

233 234 235 236

237 238 239 240

241 242 243 244

245 246 247 248

249 250 251 252

253 254 255 256

257 258 259 260

261 262 263 264

265 266 267 268

269 270 271 272

273 274 275 276

277 278 279 280

281 282 283 284

285 286 287 288

289 290 291 292

293 294 295 296

297 298 299 300

301 302 303 304

305 306 307 308

309 310 311 312

313 314 315 316

317 318 319 320

321 322 323 324

325 326 327 328

329 330 331 332

333 334 335 336

337 338 339 340

341 342 343 344

345 346 347 348

349 350 351 352

353 354 355 356

357 358 359 360

361 362 363 364

365 366 367 368

369 370 371 372

373 374 375 376

377 378 379 380

381 382 383 384

385 386 387 388

389 390 391 392

393 394 395 396

397 398 399 400

401 402 403 404

405 406 407 408

409 410 411 412

413 414 415 416

417 418 419 420

421 422 423 424

425 426 427 428

429 430 431 432

433 434 435 436

437 438 439 440

441 442 443 444

445 446 447 448

449 450 451 452

453 454 455 456

457 458 459 460

461 462 463 464

465 466 467 468

469 470 471 472

473 474 475 476

477 478 479 480

481 482 483 484

485 486 487 488

489 490 491 492

493 494 495 496

497 498 499 500

501 502 503 504

505 506 507 508

509 510 511 512

513 514 515 516

517 518 519 520

521 522 523 524

525 526 527 528

529 530 531 532

533 534 535 536

537 538 539 540

541 542 543 544

545 546 547 548

549 550 551 552

553 554 555 556

557 558 559 560

561 562 563 564

565 566 567 568

569 570 571 572

573 574 575 576

577 578 579 580

581 582 583 584

585 586 587 588

589 590 591 592

593 594 595 596

597 598 599 600

601 602 603 604

605 606 607 608

609 610 611 612

613 614 615 616

617 618 619 620

621 622 623 624

625 626 627 628

629 630 631 632

633 634 635 636

637 638 639 640

641 642 643 644

645 646 647 648

649 650 651 652

653 654 655 656

657 658 659 660

661 662 663 664

665 666 667 668

669 670 671 672

673 674 675 676

677 678 679 680

681 682 683 684

685 686 687 688

689 690 691 692

693 694 695 696

697 698 699 700

701 702 703 704

705 706 707 708

709 710 711 712

713 714 715 716

717 718 719 720

721 722 723 724

725 726 727 728

729 730 731 732

733 734 735 736

737 738 739 740

741 742 743 744

745 746 747 748

749 750 751 752

753 754 755 756

757 758 759 760

761 762 763 764

765 766 767 768

769 770 771 772

773 774 775 776

777 778 779 780

781 782 783 784

785 786 787 788

789 790 791 792

793 794 795 796

797 798 799 800

801 802 803 804

805 806 807 808

809 810 811 812

813 814 815 816

817 818 819 820

821 822 823 824

825 826 827 828

829 830 831 832

833 834 835 836

837 838 839 840

841 842 843 844

845 846 847 848

849 850 851 852

853 854 855 856

857 858 859 860

861 862 863 864

865 866 867 868

869 870 871 872

873 874 875 876

877 878 879 880

881 882 883 884

885 886 887 888

889 890 891 892

893 894 895 896

897 898 899 900

901 902 903 904

905 906 907 908

909 910 911 912

913 914 915 916